

# ULLTRA colorline

## LATEX

### EMULSION PAINT

#### GENERAL CHARACTERISTICS

High quality emulsion paint for interior use. It can be used for the painting of new surfaces, walls, plasters and cementitious surfaces, which have been well prepared with the suitable primer. It combines great covering properties, levelling, excellent whiteness and is easy to work with. It is an inexpensive solution for surfaces that are often repainted.

#### TECHNICAL CHARACTERISTICS

**Texture:** Flat with sheen up to 6-10 units at 85° .

**Specific gravity:** 1,55 – 1,58 kg/lit.

**Covering power:** 11 - 13 m<sup>2</sup> /lit per layer depending on the surface.

**Dilution:** 5 – 10% on volume with water

**VOC class :** "Interior mat coatings for walls and ceilings". Type Y. VOC limit = 30gr/lit. Max VOC of product ready for use = 15 gr/lit. It fulfils the requirements of E.C. legislation after 2011. VOC: organic volatile compounds with boiling point < 250°C.

**Drying:** Dry to touch in 1 - 2 hours. The paint adopts full resistance in washing 3 - 4 weeks after application.

**Recoatibility:** 3-6 hours. These times could elongate under cold and wet weather conditions.

**Color shades:** White

**PACKING:** White: 3lt & 9lt.

**APPLICATION EQUIPMENT:** Brush, roller and AIRLESS spray.

#### SURFACE PREPARATION

Clean the surface of dust, oil, cropped paints and dampness. Sandpaper well. Surfaces painted with white lime, glue, old paints or, new surfaces shall be painted before with **Acrylic primer**. Dirty surfaces (nicotine, dump, smoke) are primed with SMALTOX primer.

#### APPLICATION

Stir well before use. Apply two coats **ULLTRA colorline LATEX**.

#### CLEANING EQUIPMENT

While working keep your equipment wet, either in the pot or in the paint launder. Strain well your tools from paint back to the pot and clean immediately with water and soap. If paint dries on your tools, it can be removed only with strong detergents.

#### APPLICATION CONDITIONS

Temperature 8-30° C and relative humidity lower than 80%. New cementitious surfaces could be dried 3 – 4 weeks before priming. Adverse weather conditions may degrade paint's quality.

**STORAGE CONDITIONS**

Close container well after application, so that it is properly kept for future use. Store in a cool place. Protect from freezing and sun exposure.

**SAFETY INSTRUCTIONS**

- Keep out of the reach of children.

**LABELLING**

**ULTRA colorline LATEX** needs no danger symbols according to EC legislation.